


## piececool





Please use the clipper to cut the nozzle position and remove the parts.

d. Retaining the parts



Insert the hole, bending tab with angle 90°


Insert the hole, twisting tab with angle 90°

Attention:


Engraved / Color side


NE Non-engraved / Silver side Attention Point

Keep the parts symmetrical




Identify the insert tab, fold line and the insert hole.








When cutting metal parts, please do not cut the "insert tab" as "nozzle position". Only cut the parts of the current step when cutting the parts. Do not cut all the parts at one time to avoid loss.


When encountering the parts of the folding line, please pay attention to the front and back of the metal sheet and the direction of the folding. According to the direction indicated in the instruction, cut lightly and fold slowly. It is best to fold it once. Do not fold it repeatedly to avoid damage to the parts.















































Step38

