


piececool





Please use the clipper to cut the nozzle position and remove the parts.

d. Retaining the parts




Insert the hole, bending tab with angle 90°


Attention:




NE Non-engraved / Silver side

Attention Point Keep the parts symmetrical











When cutting metal parts, please do not cut the "insert tab" as "nozzle position". Only cut the parts of the current step when cutting the parts. Do not cut all the parts at one time to avoid loss.


When encountering the parts of the folding line, please pay attention to the front and back of the metal sheet and the direction of the folding. According to the direction indicated in the instruction, cut lightly and fold slowly. It is best to fold it once. Do not fold it repeatedly to avoid damage to the parts.

















39 X7

